

**Saudi Reference List: Rotary Electrical and Partners/Subcontractors****Residual Life Assessments Plus extra Works**

<u>City</u>	<u>PP No</u>	<u>Unit No</u>	<u>Type</u>	<u>Year</u>
Al Baha		3	ASEA15.5MVA	2006 Plus Partial Stator Rewind
Asir		1	GE 98.7MVA	2004 Plus Major Overhaul
Duba		1	GE 5001-B	2010
Duba		3	GE 5001-B	2010
Ghazlan			Westinghouse	2004 Plus Major Overhaul
Jeddah	2	4	GE MS 5001L	2004
Jeddah	2	7	ABB 11B	2008
Jeddah	2	8	ABB 11 B	2010
Jeddah	2	10	ABB 11B	2005
Jeddah	2	11	Westinghouse	2004
Jeddah	3	1	GE 7001-B	2006
Jeddah	3	1	GE 7001-B	2009
Jeddah	3	2	GE 7001-B	2008
Jeddah	3	3	GE 7001-B	2002
Jeddah	3	3	GE 7001-B	2005
Jeddah	3	3	GE 7001-B	2009
Jeddah	3	4	GE MS 5001L	2005
Jeddah	3	4	GE MS 7001B	2007
Jeddah	3	5	GE 7001-B	2008
Jeddah	3	6	GE 7001-B	2009
Jeddah	3	7	GE 7001-B	2009
Jeddah	3	8	GE 7001-B	2004
Jeddah	3	8	GE 7001-B	2010
Jeddah	3	9	GE 7001-B	2004
Jeddah	3	9	GE 7001-B	2009
Jeddah	3	11	GE 7001-B	2005
Jeddah	3	11	GE 7001-B	2010
Jeddah	3	12	ABB 11D5	2005
Jeddah	3	12	ABB 11 D5	2008
Jeddah	3	12	ABB 11 D5	2010
Jeddah	3	13	ABB 11D5	2007
Jeddah	3	15	ABB 11 D5	2010
Jeddah	3	17	ABB 11 D5	2010
Jeddah	3	18	ABB 11 D5	2010
Jeddah	3	19	ABB 11D5	2007
Jeddah	3	21	ABB 11D5	2007
Jeddah	3	23	ABB 11 D5	2010
Jeddah	3	24	ABB 11 D5	2010
Jeddah	3	25	ABB 11 D5	2010
Jeddah	3	26	ABB 11 D5	2010
Jeddah	3	27	ABB 11D5	2007
Jeddah	3	27	ABB 11 D5	2010
Jeddah				2004 Stator Rewind
Jizan		2	GE 29.6MVA	2004 Plus Major Overhaul
Jizan		4	GE 29.6MVA	2004 Plus Major Overhaul
Jizan		5	GE 45.3 MVA	2004 Plus Major Overhaul
Jizan		6	GE 45.3 MVA	2004 Plus Major Overhaul
Jizan		8	GE 29.6MVA	2004 Plus Major Overhaul
Jizan		12	Hitachi	2004 Plus Major Overhaul
Madinah	1	3	ABB 9C	2007
Madinah	1	4	GE FR5	2002
Madinah	1	4	GE FR5	2004
Madinah	2	1	ABB 9D	2007

Madinah	2	5 ABB 9D	2007
Madinah	2	7 ABB 11D5	2007
Madinah		2 ABB 9D	2010
Makkah		3 ABB 9D	2010
Makkah		4 GE MS 7001B	2007
Makkah		5 GE 7A3	2004
Makkah		5 GE 7A3	2010
Makkah		6 GE 7001-B	2004
Makkah		6 GE 7001-B	2009
Makkah		7 ABB 11D5	2004
Makkah		7 ABB 11D5	2009
Makkah		8 ABB 11D5	2008
Makkah		8 ABB 11D5	2009
Makkah		8 ABB 11 D5	2010
Makkah		9 ABB 11D5	2009
Makkah		10 ABB 11D5	2009
Makkah		11 ABB 11 D5	2010
Makkah		12 ABB 11D5	2009
Makkah		13 GE 7001-B	2009
Makkah		14 GE 7001-E	2005
Makkah		14 GE 7001-E	2008
Makkah		15 GE 7001-E	2005
Makkah		16 GE 7001-E	2008
Makkah		17 GE FR 7	2006
Makkah		18 GE 5001-B	2006
Makkah		18 GE 5001-B	2010
Rabigh		1 ABB 11D5	2008
Rabigh		2 ABB 11D5	2008
Rabigh		3 ABB 11D5	2007
Rabigh		4 ABB 11D5	2007
Rabigh		5 ABB 11D5	2008
Rabigh		7 ABB 11D5	2008
Rabigh		8 ABB 11D5	2007
Riyadh	7	5 GE 7A3	2001
Riyadh	7	6 GE 7A3	2001
Riyadh	7	7 GE 7A3	2005
Riyadh	7	8 GE 7A3	2001
Riyadh	7	9 GE 7A3	2001
Riyadh	7	10 GE 7A3	2001
Riyadh	7	11 GE 7A3	2001
Riyadh	7	12 GE 7A3	2001
Riyadh	7	13 GE 7A3	2004
Riyadh	7	14 GE 7A3	2001
Riyadh	7	15 GE 7A3	2004
Riyadh	7	16 GE 7A3	2002
Tabuk	1	1 GE MS 5001	2008
Tabuk	1	2 GE FR5	2004
Tabuk	1	3 GE MS 5001	2007
Tabuk	1	4 GE MS 5001	2007
Tabuk	2	1 GE 6001-B	2008 Plus Retaining Ring Replacement
Tabuk	2	2 GE 6001-B	2008
Taif		3 AEG 32 MVA	2010 Plus Major Overhaul
Taif		5 ABB 9D1N	2010
Tihama		2 GE 42.1MVA	2004 Plus Major Overhaul
Yanbu		1 GE MS 5001	2007
Yanbu		2 GE MS 5001	2007
Yanbu		3 GE MS 5001	2004